

**Product Discontinuation
Notices**

August 1, 2011

Photoelectric Sensors

No. 2011231E-2

Discontinuation Notice of E39-[] series (for china area only)

Product Discontinuation

Recommended Replacement



**E39-FU[]
E39-UF1-10**



No recommended replacement

Discontinuation date : The end of March, 2012

Product Discontinuation and recommended replacement

Product discontinuation	Recommended replacement
E39-FU1	No recommended replacement
E39-FU1-1	
E39-UF1-10	